

LID DAMPER / BOWL DAMPER REPLACEMENT INSTRUCTIONS

▲ WARNING: GENUINE WEBER-STEPHEN REPLACEMENT PARTS MUST BE USED FOR ANY REPAIR OR REPLACEMENT. YOUR ACTIONS, IF YOU FAIL TO FOLLOW THIS PRODUCT WARNING, MAY CAUSE A STRUCTURAL FAILURE, OR FIRE RESULTING IN SERIOUS PERSONAL INJURY OR DAMAGE TO PROPERTY.

(WILL VOID ALL WARRANTY PROTECTION)

▲ IMPORTANT NOTE: REMOVE LID AND GRATES BEFORE PERFORMING ANY WORK. MAKE SURE THE KETTLE IS COLD AND ALL CHARCOAL RESIDUE IS REMOVED FROM THE KETTLE BOWL AREA.





▲ WARNING: Make sure that all parts are assembled and hardware is fully tightened before operating the grill. Your actions, if you fail to follow this Product Warning, may cause a structural failure, or fire resulting in serious personal injury or damage to property.



WEBER-STEPHEN PRODUCTS LLC Customer Service Center 1890 Roselle Road, Suite 308 Schaumburg, IL 60195

> 1-800-446-1071 (USA ONLY) www.weber.com®

Contact the Customer Service Representative in your area using the contact information on our website.