

HESTAN

**Kpf wevkqp 'T cpi gvqr
MTVK52
Rct vu'Nku**

**J gucp'Ego o gteknEqtrqtcvkqp
5597'G0Nc'Rem c'Cxg0
Cpcj glo .'EC''; 4: 28
* :: †; 27/9685
TGVCKP 'VJ KUHQ'T'HWWTG'TGHGTGPEG**

K F B; '8 5; F5 A

30" INDUCTION UNIT

L1 L2 L3 N1 N2 GND
1 2 3 4 5 6

JPR JPR JPR

JUMPER
035510
3-PLCS

BLK

RED

GRN

RANGETOP
WIRE HARNESS # 034743

FLEX CONDUIT

POWER IN

"CAUTION: LABEL ALL WIRES PRIOR TO
DISCONNECTION WHEN SERVICING THE UNIT.
WIRING ERRORS CAN CAUSE IMPROPER AND
DANGEROUS OPERATION."
"VERIFY PROPER OPERATION AFTER SERVICING."

€Hííí